

B-36229 Extra Work Summary

T Wall 4 Architectural Repair following Vehicle accident with No Accident Report

7/8/2021

Description	Quantity	Unit	Unit \$	Cost	Markup	Sub-Total	1.4% B&I	TOTAL	CO Unit \$	TOTAL \$	
Wall 4 Architectural Repair	\$ 3,200.00	LS	\$	1.00	\$ 3,200.00	\$ -	\$ 3,200.00	\$ 44.80	\$ 3,244.80	\$ 1.01	\$ 3,232.00
						\$ 3,200.00					\$ 3,232.00
Bond and Insurance (0.0129)				\$ 41.28		\$ 41.28					
						1.3%					
						\$ 3,241.28					