LEIBOLD IRRIGATION, INC.



Phone 815-747-6024 Fax 815-747-6103

February 21, 2023

Mr. Daniel Augdahl Centennial Park Golf Course 1005 South Centennial Drive Munster, IN 46321

RE: Range Field Tap Relocation

The following is the proposed pricing to relocate the 4" feed to the driving range and eliminate the existing feed. The following applies:

- Install new 4" Isolation valve to south side of existing building.
- Install approximately 180' of 4" pipe to feed the driving range.
- Cut/Cap existing 2" lateral that feeds rear line of the range tee.
 - o Reinstall post construction.
- Cut existing 3" landscape irrigation loop, install 2 1" quick coupling valves for water access at dead ends.
- Remove existing 4" valve and tee. Repair 6" pipe through.
- Backfill and restore area.
- Reinstall sod if available.
- No reinstallation of 3" landscape loop assumed; this may be negotiated at a later date.
- Price assumes no permits or bonds.

Estimate per described above: \$55,900.00

If you have any questions or concerns about the above proposal, please do hesitate to call.

Regards,

Mike Skopik Leibold Irrigation, Inc. 563-564-6908