

## April Production Report

**04/07/15 – 05/07/15**

### GE Jenbacher J-320 Engine

#### Run Hours:

04/07/15: 17453

05/07/15: 18088

= 635 hours ( 88% uptime)

#### Active Energy Counter:

04/07/15: 15643 mw-hr

05/07/15: 16138 mw-hr

495= MW HR Produced

### GE HRS ORC

#### Run Hours:

05/07/15: 4432

= 0 Run Hours (0% Up Time)

### Events:

1. ORC still down awaiting completion of Isolation Transformer install from IPG. GE engineering is reviewing electrical connections and scheduling startup. No date has been finalized yet.
2. 4/17 Utility Trip 330 am to 445 am.
3. 4/17 Coolant Pump failure due to hard stop from Utility Trip down from 4/17 415pm to 4/18 1215 pm.
4. 4/21 Fire alarm sensor failure caused shutdown from 0115 am to 0630 am
5. 4/25 Short in wire from fire alarm sensor caused shutdown from 0100 am to 0630 am.
6. 4/27 Fire Alarm sensor failure caused shutdown at 0100 am, engine left down for maintenance. Restarted 4/29 at 1045 am.
7. 4/29 Engine tuned for emissions.